

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Gladwin Located In _____ Corner Code # _____
 (County)

- | | | | | | |
|--------------------------------------|---------|--------------|-------------|--|-------|
| 1. Public Land Survey | | T <u>19N</u> | R <u>2E</u> | | L1 |
| | | T _____ | R _____ | | _____ |
| 2. Property Controlling in Section | S _____ | T _____ | R _____ | | _____ |
| | S _____ | T _____ | R _____ | | _____ |
| 3. Miscellaneous Property in Section | S _____ | T _____ | R _____ | | _____ |
| | S _____ | T _____ | R _____ | | _____ |

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on May 2, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5				4				3	2
3													1
4	7			8				9				10	11
5													12
6	18			17				16				15	14
7													13
8	19			20				21				22	23
9													24
10	30			29				28				27	26
11													25
12	31			32				33				34	35
13													36

A. Description of original monument and accessories and/or subsequent restoration:

- L1 - GLO - None
 - CCC Notes - 1930's - W. 40 CH. - Set Random in Marsh
 1/4 post is 31N and 5 1/2 E of Random (L1 or L13?)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- L1 - Closing N 1/4 corner, Section 1, T19N, R2E - Fd. 1 1/2" iron pipe, 1.8' above ground in dry swamp. Fd. 1 1/2" pipe consistant with CCC monumentation found to E & W and is accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- L1 - Drove stamped 2" Aluminum cap on 5/8" x 4' long rebar inside fd. 1 1/2" iron pipe.
 N64°W 20.85' to set N & T in SW side 6" Hackberry
 S50°W 94.51' to set N & T in SE side 8" R. Maple scribed 'XBT'
 N16°E 31.03' to set 1/2" x 18" tie rod
 S32°E 33.83' to set 1/2" x 24" rebar
 West 3.24 to 'L13' T20N, R2E - Fd. 1 1/2" pipe - Add 2" Alum. Cap.
 Set Blue Carsonite Post 1' South



Signed by: Craig W. McVean
 Surveyor's Michigan License No.: 39088

Date: 5/9/2007