

**SURVEY & REMONUMENTATION**

**OCT 23 1998**

GLADWIN County Remonumentation

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER **001** PAGE **224**

For corners in

GLADWIN Located in: Corner Code #  
(County)

1. Public Land Survey T20N R02E C-6  
T R  
T R  
T R

2. Property Controlling S T R  
in Section S T R

3. Miscellaneous S T R  
Property in Sec. S T R

STATE OF MICHIGAN  
GLADWIN COUNTY  
FILED-CORNER

13 OCT 1998 12:46:58 PM

BONNIE K. HOUSE  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Mark R Robison, in a field survey on May, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   |

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate**

A. Description of original monument and accessories and/or subsequent restoration:

**C-6:** 1846 John Mullett Set 1/4 Sec Post  
Wit-(1)Maple 10 N76E 4  
(2)Cedar 10 S57W 25

1967 Henning survey Wit-none

1972 Edmands Eng. LCRC#50 3/8" Iron  
Wit-(3)N16°50'W 136.25 P.P.  
(4)S14W 178.95 P.P.  
(5)47.75 East P.P.

1996 DNR LCRC#371 Set 5/8" x 16" rerod  
Wit-(6)Cut nail N20E 11.36  
(7)Ced Post with P.K. N85W 19.00  
(8)Poplar S84E 45.23

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**C-6:** Found 5/8" x 16" capped iron (DNR) 1 ft. West of centerline North-South road, 11 ft. +/- South of old post on East Right-of-Way line. Agrees with LCRC#371 witnesses. Excavated; found no other corners. Corner agrees with 1967 survey by Henning. Set Gladwin County Remonumentation in place of found corner.

See dossier for additional information.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**C-6:** Corner common to Sections 17 & 18. Set 5/8" x 36" rerod in Monument Box with Gladwin County Remonumentation cap marked P.S.#27458.

Witnesses:

East 5/8" x 36" Rerod 16.79' (set)  
N30E 5/8" x 16" Capped Iron 44.20' (set)  
N20E Cedar Post, P.K. Nail, 17.00'  
S84E Poplar, spike, 45.23'  
P.K. Nail 2 ft. North & East

APPROVED LAND CORNER  
P.A. 315 of 1990  
Gladwin County

Co. Rep. [Signature]  
Date 5/11/98

Signed by [Signature]



Surveyor's Michigan License No. 27458

Date 10 23 98