

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
GLADWIN

(County)

Located In:

Corner Code \neq

- | | | |
|------------------------------------|----------------------------|------------------|
| 1. Public Land Survey | T <u>20N</u> R <u>2E</u> | <u>H-1, I-1,</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S <u>3</u> T _____ R _____ | <u>1, 15</u> |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, CARL F. ROSER, in a field survey on MAY 6, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(NO EVIDENCE OF G.L.O. CORNER, B.T'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-1	I-1	I	15
ESTABLISHED N 1/4 COR S-3 MIDWAY BETWEEN NW & NE COR'S OF S-3 & DN LINE BETWEEN FD S 1/4 S-32, T21N-R2E & REESTABLISHED SW COR S-32, T21N-R2E. E-W SMOOTH WIRE ON TREES IS 61' SOUTH.	FD PIPE FOR NW COR S-2. J. MEYERS FD 2" PIPE & USED IT IN 1991 CERT OF SURVEY IN W 1/2 OF S-2. WE MEAS 1 1/2" I.D. PIPE. ALL THREE J. MEYERS WITS FIT OK.	ESTABLISHED NE COR OF FRL W 1/2 OF FRL W 1/2 OF FRL. S-3 PER STANDARD BLM INSTRUCTIONS.	ESTABLISHED THE SE COR OF FRL W 1/2 OF FRL W 1/2 OF FRL. S-3 PER STANDARD BLM INSTRUCTIONS. CTR OF DIRT RD WEST & SE'LY IS 73' SOUTH.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-1	I-1	I	15
SET DNR MON & CEDAR POST, 3" R PINE N15°E 43.2'	FD OLD 1 1/2" PIPE.	DROVE 5/8" X 3/4" REROD W/RLS CAP & SET CED POST W/LOC TAG.	DR 5/8" X 3/4" REROD W/RLS CAP. SET CED POST W/LOC TAG.
25" R PINE S58°E 46.6'	13" MAPLE N55°W 60.54'	9" MAPLE S55°E 11.6'	POWER POLE S50°W 62.80'
7" MAPL(CLP 4) SOUTH 29.4'	21" TRPL B OAK N75°E 51.85'	6" OAK S02°E 38.0'	4" W PINE S85°W 52.10'
24" R PINE S50°W 25.9'	8" B OAK S85°W 29.81'	2" TM MAPLE S60°W 24.4'	6" W PINE N40°W 27.92'
DNR MON; S1/4 S-32 T21N-R2E N88°25'E 3.47'	SE COR S-32, DNR MON T21N-R2E N88°31'E 141.20'	SW COR SE-SW S-32 (21N-2E), SET REROD S88°25'W 69.87'	SW COR POLE BLDG N20°E 22.3'
	8 LLS J. MEYERS WIT.		SE COR POLE BLDG N60°E 38.2'

Signed by Carl F. Roser 12028
 Surveyor's Michigan License No. _____

Date 9-27-95

