

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51. NR. 36. W

H o u g h t o n COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 22 and 23

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 13" Hard Maple (1/4s NBT) N 83° W 12 1/2 Links

12" Hard Maple (1/4s NBT) N 64° E 45 Links

10" Soft Maple (1/4s NBT) S 24° E 32 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established 2.47 chains north of a Yellow Birch line tree. Line tree is down but in fair condition. No evidence of Original corner. Corner is on a north-south blazed line.

Corner was placed and witnessed October 8, 1959.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/29/60