

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

HOUGHTON COUNTY

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 52N <sup>N.</sup> <del>X.</del> R. 35 <sup>E.</sup> <del>W.</del>	H-12, C-11
2. PROPERTY CONTROLLING IN SECTION 34	T. 52 <sup>N.</sup> <del>X.</del> R. 35 <sup>E.</sup> <del>W.</del>	5
3. MISCELLANEOUS PROPERTY IN SECTION	T. <sup>N.</sup> <del>S.</del> R. <sup>E.</sup> <del>W.</del>	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:  
**Corner H-12:** Not set on original survey. This corner was set by P.A. Larsen in 1925. It appears to have been set by proper procedures.  
**Corner 5:** Not set on original survey nor subsequently apparently.  
**Corner C-11:** Original monument and accessories not found. Found a few old blazes in area.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
**Corner H-12:** Restored at 1 1/2" I.D. Iron Pipe set by P.A. Larsen in 1925.  
**Corner 5:** Established 5-26-82 on line and midway between 1/4 corner north and center 1/4 corner south.  
**Corner C-11:** Restored 6-1-82 at record distance from section corner west and from land calls north. This position best fits this corner in my judgment.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
**Corner H-12:** Found 1 1/2" I.D. Iron Pipe  
 7" Y. Birch N61E 14.7 ft. 1/4S, BT  
 7" Y. Birch N16W 12.8 ft. 1/4S, BT  
 5" Y. Birch S01W 17.1 ft. 1/4S, BT  
 7" Maple squared south 1.3 ft.  
**Corner C-11:** Set 1" I.D. by 32" Iron Pipe w/4" alum. cap.  
 12" W. Pine S73W 38.3 ft. S31, NBT  
 6" B. Ash N71W 5.0 ft. S30, NBT  
 16" Hemlock S62E 18.4 ft. S32, NBT  
**Corner 5:** Set 1" I.D. by 32" Iron Pipe w/4" alum. cap.  
 5" Maple S41W 13.8 ft. 1/16S, BT  
 5" Sugar S75E 15.5 ft 1/16S, BT  
 6" Maple N58W 21.4 ft 1/16S, BT  
 10" aspen squared S25W 2.7 ft.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Keith L. Sackett DATE 2/6/83

MICHIGAN REGISTERED LAND SURVEYOR  
 Keith L. Sackett  
 Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006

