

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 31 W


Iron COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 17 and 18

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/19/60

WITNESSES TO CORNER..... 10" Elm (1/4s NBT) S 06° E 38 Links



7" H. Maple (1/4s NBT) N 25° W 36 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at Iron Pipe set by unknown Surveyor. Have report of a wood stake in this position in 1941, found by Wisconsin-Michigan Power Company Surveyors. Position checks well with other corners in area.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE

3/17/61