

SURVEY & REMONUMENTATION

FORM NO. 985-A



MAR 19 1997

Stock No. 26273

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

_____ Iron _____ (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 35W	K-13
	T 45N R 35W	K-1
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous	S _____ T _____ R _____	_____
Property in Sec.	S _____ T _____ R _____	_____

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

96 DEC 23 AM 8:50

L.C. Records L.7, P. 23

Gilbert Siles
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner 35 & 36 T46N R35W
2 & 1 T45N R35W

I, Gary L. Pisoni, in a field survey on October 10, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William Burt, U.S. Deputy Surveyor in 1846.
Original corner: Wood Post
Original bearing trees:
Hemlock 10" N 49° E 32 links (21.12 feet)
Yellow Birch 24" N 11° W 32 links (21.12 feet)
Yellow Birch 14" S 82° W 10 links (6.60 feet)
Maple 10" S 58° E 37 links (24.42 feet)

In 1969, Donald D. Lappala, R.L.S. set a 2" dia. Concrete filled galvanized pipe with brass tablet from a found 4" x 4" Cedar post and evidence from original bearing trees as described above.
Recorded in Land Corner Certificate L. 3, Page 227 on June 5, 1969.

1969 Bearing Trees:
Sugar Maple 5" N 43° W 15.1 feet
Yellow Birch 5" S 72° E 25.0 feet
Sugar Maple 4" S 15° E 16.0 feet

PEER GROUP APPROVED
Pisoni Gary L. Pisoni 12-11-96
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the monument and bearing trees as described above:
Sugar Maple 8" N 43° W 15.01 feet
Yellow Birch 12" S 71° E 24.91 feet
Sugar Maple 5" S 14° E 15.97 feet

Corner Record Research on file with County Representative.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (all measurements taken to a nail in side of tree)
Red Maple 8" S 71° W 50.77 feet
Steel Sign Post 6" North 0.70 feet

#96-1
Signed by Gary L. Pisoni Date 12-10-96
Surveyor's Michigan License No. 27457

L.7 P.23