

1/2

SURVEY & REMONUMENTATION

MAR 03 1998

KENT COUNTY REMONUMENTATION

"other" code #4

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KENT COUNTY

(County)

Located in:

Corner Code #

1. Public Land Survey

T	_____	R	_____
T	_____	R	_____
T	_____	R	_____
T	_____	R	_____

2. Property Controlling in Section

S	<u>23</u>	T	<u>5N</u>	R	<u>9W</u>	Wit. Mon. on
S	_____	T	_____	R	_____	E-W 1/4 line

3. Miscellaneous Property in Sec.

S	_____	T	_____	R	_____
S	_____	T	_____	R	_____

REC. OF DEEDS
David Bond
 97 OCT 14 AM 10:30
 STATE OF MICHIGAN
 COUNTY OF KENT
 RECEIVED FOR RECORD
10054
 Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Kirk Breitels, in a field survey on July 23, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
 No Information - Not Set
 See LCRC # 10053 for Central 1/4 corner (J-8) of Sec. 23

P.A. 345 1990 KENT COUNTY
 PEER APPROVED 8/28/97
 CHAIRMAN *Harry Huber*

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 Established point on E-W 1/4 line 330.00' East of the C 1/4 corner. This point is also a property corner per descriptions.

This point is on remains of fence to North ± and is 5'± North of remains of fence to East.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 Set Harrison Monument with witness cap at point described above.

- Nail & KC Remon. tag S. side 8" thorn tree S70°E 21.29'
- Nail & KC Remon. tag N. side 30" Cherry N80°E 42.02'
- Nail & KC Remon. tag SE side 6" Hickory N60°E 42.00'
- Nail & KC Remon. tag W. side 10" Cherry N10°E 35.03'



Signed by Kirk Breitels
 Surveyor's Michigan License No. 30077

Date 9/5/97