

JAN 21 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For corners in

- Mackinac County Located in: Corner Code #
1. Public Land Survey T42N R01W C-6
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. Recorded Plat
5. Private Claims

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGISTER OF DEEDS

DEC 31 1998

AM P/A
10 11 12 13 14 15 16

Register of Deeds Stamp & File Number

Grid with columns A-M and rows 1-13. Contains handwritten annotations 'T42N' and 'R01W' and a dot at grid position (6,17).

I, Neil E. Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1845 GLO Notes J Mullett 6" Aspen for 1/4 post
1957 DNR Billy Buckler 10" W Spruce S 59 E 70 lks
Set 1" pipe with 4" brass cap 10" Aspen N 53 E 58.5 lks
midway and online
Liber 2, page 300

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON 12-04-98 NEH

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1998 Fd 1" pipe with brass cap and 2 witnesses
Corner Found to be 0.53' East and 2.94' North of true location
Accepted corner as long standing location

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1" pipe with 4" brass DNR cap
Corner is approx 120' West of a N-S power line

- 10" W Spruce S 59 E 46.20'
10" Aspen S 53 E 38.61'
5" Balsam Due N 7.90'
8" Spruce S 07 W 38.00'
16" Spruce S 59 E 46.70'



Bearings are compass bearings, corrected for declination, all distances are to a double-headed nail in the side of the witness object unless otherwise noted.

Signed by Neil E. Hill P.S.

Date 12-29-98

Surveyor's Michigan License No. 27447