

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 28-29

CORNER MONUMENT 1" Pipe with 1/2" Aluminum Cap (buried)

DATE MONUMENT PLACED AND WITNESSED 9-28-62

WITNESSES TO CORNER..... 13" Red Pine (1/4S NBT) N 60° W 27 1/2 links



11" " " (1/4S NBT) N 82° E 77 links

12" " " (1/4S NBT) S 12° W 96 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Section Corners.  
Corner lies in line with Road to North and 1/2 links North of Road to East.  
No evidence of original Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64  
REGISTERED LAND SURVEYOR  
Billy D. Buckler