

1993

1993: Mackinac County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Mackinac

(County)

Located In:

Corner Code =#

- 1. Public Land Survey T 43N R 2W C-4  
T \_\_\_ R \_\_\_  
T \_\_\_ R \_\_\_  
T \_\_\_ R \_\_\_
- 2. Property Controlling S \_\_\_ T \_\_\_ R \_\_\_  
in Section S \_\_\_ T \_\_\_ R \_\_\_
- 3. Miscellaneous S \_\_\_ T \_\_\_ R \_\_\_  
Property in Sec. S \_\_\_ T \_\_\_ R \_\_\_

RECEIVED & FILED  
DIANE L. JOHNSON  
MACKINAC COUNTY REGISTER OF DEEDS

OCT 28 1993

A/A PM  
7:59:10 PM

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, David B. Guthrie in a field survey on June 10, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845: Established by J.H. Mullett, G.L.O Survey  
Set a wood post and referenced

8" Fir - S82°E - 6 Links  
10" Sugar - S30°W - 8 Links

1987: Survey by Richard L. Hays of Nordlund & Assoc. for U.S. Forest Service.  
1989.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found a 2½" x 3' aluminum monument with a 3" aluminum cap stamped to identify the corner. This corner was set in 1989 by Richard L. Hays, P.S. No. 25847, by single proportionate measurement between the Northeast and Southeast corners of Section 7. The corner was recorded November 30, 1989. (Book D, page 44)

Plat of Survey Recorded as U.S. Gov't. Plat of Survey No. 14.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: N48°W - 43.28 feet - (R=43.25') - 6" Ash  
S31°W - 46.53 feet - 6" Spruce  
S74°E - 93.62 feet - 8" Spruce  
S66°W - 12.88 feet - 4" Spruce  
North - 2.60 feet - Steel Post

(Tree references are blazed and tagged )

The monument is a 2½"x3' aluminum monument with a 3" aluminum cap stamped to identify the corner.



Signed by David B. Guthrie

Date Sept. 27, 1993

Surveyor's Michigan License No. 22435