

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Mackinac & Luce COUNTY


T 44-5N R 9W

DESCRIPTION OF CORNER 1/4 cer. bet. Secs. 1-36

CORNER MONUMENT 2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 5-9-68

WITNESSES TO CORNER..... 9" twin hard maple (1/8 NBT) N1°W 66.2'



14" Elm (1/8 NBT) S20°E 59.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor.
Found iron pipe and wood post in place.
Cer. in an opening, near the west edge.
Cer. found by survey crew while making retracement of area.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE

3-24-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68