

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Mackinac COUNTY
T 44N R 8-9W

DESCRIPTION OF CORNER 1/2 Corner bet. Secs. 13-18

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 3-31-69

WITNESSES TO CORNER..... 9" Cedar (1/2 S NBT) S43°E 7.6'



16" Cedar (1/2 S NBT) N61°E 30.2

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by simple proportionate measure along the township line.

Found no evidence of original cor.

Cor. lies in a thick cedar swamp.

SURVEYOR'S SEAL

Billy D. Buckler

SIGNED

Billy D. Buckler

DATE

4-22-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68