

1993

COMMISSION

JOB NUMBER: 93300
SHEET NO. : 1-423

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE
(County)

Located In:

Corner Code #

1. Public Land Survey	T 46N	R 24W	B-13
	T 45N	R 24W	B-1
2. Property Controlling in Section	S	T	R
	S	T	R
	S	T	R
3. Miscellaneous Property in Sec.	S	T	R
	S	T	R

LIBER 1 PAGE 87
Register of Deeds Stamp & File Number

2003 DEC 30 PM 1:07
MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORDING

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, GERALD W. CARLSON, in a field survey on Friday, December 24, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules theretore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-1: Quarter Corner common to Section 31, T46N-R24W and Section 6, T45N-R24W. 1844: William Burt's original survey notes describe the corner monument as a wood post referenced by:
 4" Spruce Pine N25E, 19 l
 4" Spruce Pine N28W, 15 l

1945 - MCRC field book 697 indicate the iron pipe and post with coordinates South 9607.74 and East 12898.23 referenced by:
 4" Jack Pine S70W 11.5 ft.
 5" Jack Pine N43E 7.1 ft.

1957 - Air base maps show the corner positioned in the roadway with air base coordinates North 5224.14 and East 15965.23. No corner accessories given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Corner position calculates in traveled portion of blacktop roadway. No evidence of corner exists. The position was calculated from the 1987 Donnan survey. The two Corps of Engineers brass cap irons were found and the North 1/4 corner position was calculated by extending the line between these corners and the found NE corner of Section 6 Westerly a measured distance of 658.73 ft. (659.00 ft. Recorded). A 3/4" rebar with a 3 1/4" diameter aluminum tablet were placed in a monument box in the South bound lane of Strato Fortress Street. Peer group ratification 12-20-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Set a 3/4" rebar capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner in a monument box in the South bound lane in the Strato Fortress Street referenced by:
 SE corner of building #491 N84W 76.93 ft.
 NW corner of building #501 N80E 70.72 ft.
 NW corner of building #500 S29E 104.68 ft.
 NE corner of building #490 S46W 118.40 ft.

Corner falls in South bound lane of Strato Fortress Street, 40 ft. +/- North of the centerline of Invader Street.
 Bk. 4, Pg. 83.



Signed by Gerald W. Carlson Date 12-29-93

Surveyor's Michigan License No. 24589