

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 46 N R 26 W

DESCRIPTION OF CORNER Section corner for sections $\frac{21}{22}$
 $\frac{28}{27}$

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/20/70

WITNESSES TO CORNER..... 8" B. Spruce (S. 22) (NBT) N 48° E, 96.0'



8" J. Pine (S. 28) (NBT) S 39° W, 82.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

2" iron pipe, 4' long in place. Set corner as perpetrated by unknown surveyor.
Corner on power line R.O.W. Checks with other corners in area.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11/23/70

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68