

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	(MARQUETTE COUNTY) LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 46 N. R. 29 <input checked="" type="checkbox"/> W.	#K-6
2. PROPERTY CONTROLLING IN SECTION	13, T. 46 N. R. 29 <input checked="" type="checkbox"/> W.	#3
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner K-6 (1/4 corner between Sections 13 & 14, T46N, R29W):
 - Spruce post (Not found. No subsequent monuments found.)
 - Spruce 10 N43W 24 (Not found. No subsequent accessories found.)
 - W. Pine 24 N81E 31 (Probably found. No subsequent accessories found.)
 - Corner 3 (North 1/16 corner between Sections 13 & 14, T46N, R29W):
 - Not established in original survey nor subsequently, apparently.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- Corner K-6: Restored 10-15-79 from rotted remains of a W. Pine stump corresponding to original BT noted above. Corner set from it bears S0°03.2'W 39.977 ch. from original NW cor. of Sec. 13, is 3.00 ch. S of a swamp edge and 1.12 ch. N of a 20 ft. high rock knob, as given in original field notes. Record distance of 25.45 ch. S to stream checks - 25.46 ch. is actual distance measured.
 - Corner 3: Established 11-1-79 on line between Sec. Cor. 19.9885 ch. N and 1/4 cor. 19.9885 ch. S.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner K-6: \oplus Schiselled in rock outcrop, with a 1" I.D. x 36" iron pipe with 3-3/4" aluminum cap set in a mound of rocks over it.
 - White Pine 20 S43°W (mag.) 16.6 ft. "1/4S, NBT"
 - Tamarack 6 S84°E (mag.) 31.3 ft. "1/4S, NBT"
 - Declination 2° 00' West.
 - Corner 3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
 - Cedar 5 S53°E (mag.) 14.6 ft. "1/16S, BT"
 - Cedar 4 S18°W (mag.) 6.2 ft. "1/16S, BT"
 - Declination 1° 40' West.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger
MICHIGAN REGISTERED LAND SURVEYOR

DATE March 9, 1980

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

