

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD
1994 DEC 28 PM 5:57

JOB NUMBER: 94030
SHEET NO. : 1-508
For corners in

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Patricia L. Manley
REGISTER OF DEEDS

<u>MARQUETTE</u> (County)		Located In:	Corner Code #
1. Public Land Survey	T <u>47N</u> R <u>27W</u>		M-4
	T <u>47N</u> R <u>26W</u>		<u>A-4</u> ✓
	T _____ R _____		_____
	T _____ R _____		_____
2. Property Controlling in Section	S _____ T _____ R _____		_____
	S _____ T _____ R _____		_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____		_____
	S _____ T _____ R _____		_____
4. Lot No. _____, Recorded Plat _____			
5. Private Claims _____			

LIBER 1 PAGE 174
Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, GERALD W. CARLSON, in a field survey on Wednesday, December 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-4: East 1/4 Corner of Section 12.
1844: William A. Burt's original survey notes describe the corner monument as a post referenced by:
11" Black Ash S40W 20 l
6" Birch S07E 7 l
No date given: MAAS coordinates system indicate the East 1/4 Corner of Section 12, T47N-R27W as South 7730.40 and West 4956.57.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted a 2" solid iron 3.0' tall in swamp from search area calculated by Maas Mine coordinates. Distance South is 2611.71' (2612.62' Maas) and distance North is 2640.26' (2640.59' Maas).

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

Larry J. Bussard
DATE Dec 19, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Found 2" iron was cut off and a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner was placed over it and concreted into place.

Monument is referenced by nails in:

6" Spruce S84E 33.52 ft.
20" White Pine S26W 24.13 ft.
4" Spruce N60W 34.85 ft.
7" Twin Yellow Birch N08E 30.39 ft.

Steel sign post North 0.70 ft.

Bk. B, Pg. 67

Signed by Gerald W. Carlson

Date 12-22-94

Surveyor's Michigan License No. 24589

