

1983

JOB NUMBER: 93300

SHEET NO. : 1-262

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in MARQUETTE

Table with columns: Located In: (47N, 24W), Corner Code # (E-13), and rows for Public Land Survey, Property Controlling in Section, and Miscellaneous Property in Sec.

LIBER 1 PAGE 59 Register of Deeds Stamp & File Number
MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD
1993 DEC 29 AM 10:40

4. Lot No. , Recorded Plat
5. Private Claims

GERALD W. CARLSON Thursday, December 23 93
I, in a field survey on , 19
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Grid table with columns A-L and rows 2-13, containing numbers 1-36.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
E-13: Section Corner common to Sections 32 and 33, T47N-R24W. 1980 - G. Carlson monumented the corner with the 1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by:
10" Fir N81E, 32 1
11" Sugar N16W, 55 1
5/8" x 18" iron and RLS cap propotionately on line between the SW corner of Section 31, and the South 1/4 corner of Section 33, on the West summit of a North/South ridge on an old East/West blaze line.
6" Maple N33E 18.22 ft. 7" Maple S27E 14.20 ft.
3" Maple S30W 17.59 ft. 8" Maple N46W 4.53 ft.
21.75' East of NE cor. Sec. 5, T46N-R24W.
L4 RC, Pg. 22

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1993 - Found 5/8" iron with G. Carlson cap as peviously monumented. Distance to the West 1 mile check within 0.14 ft. distance East 1/2 mile check within 0.19 ft. Replaced 5/8" iron and RLS cap with Marquette County Survey Monument. Peer group ratification 12-6-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1993 - Replaced existing marker with a 2 1/8" diameter aluminum pipe capped with a 3/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:
10" Maple N35E 18.18 ft. Carlson NBT
7" Maple S25E 14.34 ft. Carlson NBT
3" Maple S33W 17.68 ft. Carlson NBT
8" Maple N47W 4.41 ft. Carlson NBT
Bk. 4, Pg. 71



Signed by Gerald W. Carlson 24589

Date 12-28-93

Surveyor's Michigan License No.