

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

| | | |
|--|---------------------------------------|-------------------|
| <u>Manistee</u> <small>(County)</small> | Located In: | Corner Code # |
| 1. Public Land Survey | T ___ R ___ | _____ |
| | T ___ R ___ | _____ |
| | T ___ R ___ | _____ |
| | T ___ R ___ | _____ |
| 2. Property Controlling in Section | S <u>19</u> T <u>35N</u> R <u>28W</u> | <u>14, 12, 7.</u> |
| | S ___ T ___ R ___ | _____ |
| 3. Miscellaneous Property in Sec. | S ___ T ___ R ___ | _____ |
| | S ___ T ___ R ___ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

| | | | | | | | | | | | | | |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

I, David Babbitt, in a field survey on 9/29/ 19 88, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 14. South 1/16 corner on the east section line of Section 19. Iron stake. R. Olson, March, 1949.
6" j.pine, N30W, 16.7' 8" j.pine, N70W, 12.0'
- 12. S 1/16 corner on the N-S 1/4 line of Section 19. Iron corner, R. Olson, 1949.
10" j.pine, N10E, 6.3'
10" j.pine, N60E, 13.2'
- 7. N 1/16 corner on the east section line of Section 19. Iron stake. R. Olson, 1949, Set MPOL.
14" j.pine, S40W, 28.2' 12" j.pine, North, 9.1' 10" j.pine, N40W, 23.1'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 14. Found iron stake (part of steel fence post) and Olson witnesses in place. Replaced stake with DNR monument.
- 12. Set MPOL between the south 1/4 corner and the center of Section 19. This corner falls 9.6 feet SW of Mr. Olson's iron. From Mr. Olson's drawing it is obvious that he did not follow proper section subdivision procedures. I, therefore, could not accept his iron as being the true 1/16 corner location. He did not have the south 1/4 corner located.
- 7. Set MPOL between the east 1/4 corner and the NE section corner of Section 19. Monument falls beside a section of steel fence post driven in.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|--|--|--|
| 14. DNR Monument. 5" tam. S5E, 8.65' 4" j.pine, S56W, 14.95' 4" tam. N58W, 15.7' 9" j.pine N32W, 16.3' | 12. DNR Monument. 13" j.pine. S87E, 36.55' 12" " S31E, 25.6' 6" " N27W, 42.1' 8" " N30E, 44.8' | 7. DNR Monument 14" oak, N26W, 22.5' 4" r.pine, N76E, 24.1' 14" oak, S53E, 47.2' 7" oak, S86W, 40.4' |
|--|--|--|

Signed by David B. Babbitt Date 1-26-89
 Surveyor's Michigan License No. 21558