

LIBR 17932PG769

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland (County)

Located In: Farmington Twp.

Corner Code #

1. Public Land Survey T 1-N R 9-E C-10
 T _____
 T _____
 T _____
 T _____

2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

SURVEY & REMONUMENTATION
MAR 21 2000

JA-2980002
 \$ 7.00 MISCELLANEOUS RECORDING
 \$ 2.00 REMONUMENTATION
 2 JAN 00 10:43:28 RECEIVED 12A
 OAKLAND COUNTY REMONUMENTATION COUNTY
 PEER REVIEW COMMITTEE
 LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
 Register of Deeds Stamp & File Number

SECTION

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John N. Redash, in a field survey on March 6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1817 Set Post	S. Carpenter	n/a	G.L.O. notes
1972 Not Described	F. Papke	#9675	Survey L 5911 p. 317
1972 1" Iron in 6" Section Box	F. Papke	#9675	L.C.R.C L 5911 p. 318, 319
1973 FD 1/2" Iron in Monument Box	R. Kostecke	#12584	Survey L 6185 p. 268

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 1/2" iron in monument box currently occupies this corner. Current measurements match 2 ties from L.C.R.C. L5911 P.318, 319. Field measurements were made between the following corners:

C-9 to C10	C-10 to C-11
2652.08 meas.	2652.80 meas.
2640.00 G.L.O.	2640.00 rec. G.L.O.
	2653.98 Tax Maps
	2652.82 Plats L 159 p.28-31

200 FILE ✓

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I Placed a 2" dia. Brass cap stamped "Oakland County Remonumentation PS 37281" on the existing 1/2" iron rod in monument box.

Witness ties are as follows:

N 47°E, 105.23	Centerline top nut fire hydrant
Due East, 50.73	P.K. nail and remonumentation washer N. face U-Pole
Due West, 70.93	Found "X" on fence post
N 56°W, 52.99	Centerline top nut fire hydrant



The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by John N. Redash
Surveyor's Michigan License No. 37281

Date April 24, 1997