

**SURVEY &  
REMONUMENTATION**

DEC 16 1996

**COMMISSION**

JUDITH D. ROEHM  
Ontonagon County  
LC 4/95 JEM Fee: 9.00  
Page 1 of 1

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

<u>ONTONAGON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>48NR 40W</u>	<u>I-12</u>
	T <u>  </u> R <u>  </u>	<u>  </u>
	T <u>  </u> R <u>  </u>	<u>  </u>
	T <u>  </u> R <u>  </u>	<u>  </u>
2. Property Controlling in Section	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
3. Miscellaneous Property in Sec.	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

1/4 Corner common to Sections 34 & 35, T48N R40W.

I, Earl W. Applekamp, in a field survey on May 16, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34	●	35		36		
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, May 29, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

White Birch 10" S35°E 11 links  
Cedar 6" N46°E 12 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner <sup>was</sup> will be re-established by single proportionate measurement between opposite section corners North & South.

PEER GROUP APPROVED  
Earl W. Applekamp  
COUNTY REPRESENTATIVE  
07-08-96

Research on file with the Ontonagon County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 1/2" X 30" aluminum pipe with a 3 1/4" cap stamped to read: County Remonumentation, 1/4, T48N R40W, S34, S35, 1996, P.S. 17610. I established three bearing trees and one reference object.

10" Maple S27°-50'-16"W 49.90' - 11" Oak S54°-44'-54"E 20.31'  
6" Maple N25°-14'-08"W 8.01' - Steel Sign Post West 1.07'



Signed by Earl W. Applekamp  
Surveyor's Michigan License No. 17610

Date June 8, 1996