

SURVEY &
REMONUMENTATION
1995 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

2234

JAN 17 1996
LAND CORNER RECORDATION CERTIFICATE
COMMISSION
Requirement of Act 74, Mich. P.A. 1970

LIBER 316 PAGE 317
PRESQUE ISLE COUNTY
RECORDED

95 OCT 20 PM 4:35

Janet M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in PRESQUE ISLE (County) Located In: _____ Corner Code # _____

1. Public Land Survey	T	<u>36N</u>	R	<u>2E</u>	<u>L-3</u>
	T	_____	R	_____	_____
	T	_____	R	_____	_____
	T	_____	R	_____	_____
2. Property Controlling in Section	S	_____	T	_____	R
	S	_____	T	_____	R
3. Miscellaneous Property in Section	S	_____	T	_____	R
	S	_____	T	_____	R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Ronald Bischer, in a field survey on August 8, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes - 1856 Resurvey	Restored with 1/2" Rod & RLS Cap
Geo. H. Cannon	S20°W 9.89' 6" Cedar
Set wood post	S15°E 21.98' 8" Cedar
Cedar 8" N45°W 10 1/2 lks	S45°E 19.32' 4" Cedar
Y. Pine 8" S35°E 21 lks	02-06-75, 07-28-76, 06-28-77, 06-07-82
02-04-75 - Delmar E. Porter	Delmar E. Porter - same corner and witnesses as on 02-04-75
Restored corner by extending (Scott Eng) section line & doubling the 1/8 cor. dist.	11-04-94 - Norman J. Quaine, #33984
	same cor. and witnesses as Porter - 02-04-75

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Rod and Cap #15410
S36°W 9.89' 6" Cedar
South 21.89' 12" Cedar
S54°E 19.32' 5" Cedar



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" Rod and Cap #15410
S36°W 9.89' 6" Cedar
South 21.89' 12" Cedar
S54°E 19.32' 5" Cedar
N37°E 11.29' 4" Cedar

Nails with witness tag #22428 used.

Ratified by Peer Group
in accordance with P.A. 345
Chairman Delmar E. Porter
Date 9/20/95

Signed by Ronald R. Bischer
Surveyor's Michigan License No. 22428

Date Oct. 3, 1995