

8947

FEB 18 1994

ROSCOMMON COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF ROSCOMMON
REGISTERED

Dec 16 9 20 AM '93

For corners in
Roscommon
(County)

Located In: Corner Code #

- 1. Public Land Survey T 21N R 2W L-9
- T _____ R _____
- T _____ R _____
- T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
- in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
- Property in Sec. S _____ T _____ R _____

Robert A. ...
REGISTERED

**ROSCOMMON COUNTY
PEER GROUP APPROVAL**
DATE 12-7-93

TO BE FILED IN LIBER 3 OF LAND CORNERS
Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Larry L. Cavanagh, in a field survey on November, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
W/post placed by Wm A. Burt 1850
Beech 10" N8°E 35
Hemlock 18" S40°W 53

1990 Land corner recordation L-1,P-275
1/2"x18" capped steel bar
S36°W 10" Birch 42.24
S88°E 12" Maple 10.95
N54°W 14" Maple 69.6
N32°E 18" Elm 25.13
Fence corner 18' North, 6' West

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" capped iron and all 1990 witnesses. Steel fence post driven near corner. Accepted as the best available evidence of the position of the original corner.

See filed dossier for detail of report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Roscommon Co. Std. Mon stamped L-9 17614
S36°W Nail & tag in 10" Birch 42.65
S88°E Nail & tag in 12" Maple 11.40
N54°W Nail & tag in 14" Maple 70.15
N32°E Nail & tag in 18" Elm 25.75
Old fence corner 18' North & 6' West of corner
Carsonite post North 1.55
Fence Post West 1.5



Signed by *Larry L. Cavanagh*
Surveyor's Michigan License No. 17614

Date 12-15-93

Date December 7, 1993 Peer Group Approved