

**SCHOOLCRAFT COUNTY
PEER GROUP APPROVED**

DATE May 12, 1995 **LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

JAN 30 1996
COMMISSION

For corners in

<u>Schoolcraft</u> <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey	T <u>42 N</u> R <u>15 W</u>	<u>H-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Received & Filed this 6 day of
Dec 1995 at 11:42 A M
Sigrid I. Hedberg
Schoolcraft Co. Reg. of Deeds

Register of Deeds Stamp & File Number

I, Thomas P. O'Brien, in a field survey on Nov. 7, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-7 (North 1/4 Corner of Sec. 22)
Sept. 14, 1850 Algernon Merryweather D.S. set qr. section post.
Hemlock 16 in. S42W 10 links W. Pine 14 " N7E 20 "

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-7 July 22, 1969 Frank J. Bray, RLS replaced corner from original B.T." White Pine 14" N07E 20 links" burned stump w/notch and portion of scribe marks on lower face."

Oct. 18, 1994 Thomas P. O'Brien, PS recovered 1" pipe w/ 4" aluminum DNR cap as set by Frank J. Bray, RLS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-7 1" pipe w/ 4" aluminum cap stamped to identify.
Witnesses:
8" White Birch S11°E 20.46' (tree is dead) witness by F. Bray.
8" Balsam N57°W 9.9' (tree is dead) " " " "
8" Maple S5°E 31.92'
8" Spruce N76°E 17.78'
8" Spruce N50°W 22.92'
Post North 1.5'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by Thomas P. O'Brien, PS Date Dec. 4, 1995

Surveyor's Michigan License No. 21274

LIBER 4 PAGE: 8