

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 13 - 14 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 18-19-13-24

CORNER MONUMENT 1" Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-15-62

WITNESSES TO CORNER..... 6" Jack Pine (S 18 NBT) East 07 links



12" Red Pine (S 19 NBT) S 10° E 90 1/2 links

12" Jack Pine (S 13 NBT) N 47° W 10 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportionate measure from corners 1 mile North and 2 miles South.

No evidence of original Corner.

Corner lies 1 chain North of Road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64
REGISTERED LAND SURVEYOR
Billy D. Buckler