

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 14 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 27-28-33-34

CORNER MONUMENT 1" Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-14-62

WITNESSES TO CORNER..... 5" Red Pine (NBT) N 37° W 43 1/2 links



1/4" Red Pine (NBT) N 10° E 31 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced 2,589 chains North of a 1" Iron Pipe on R.R. R.O.W. as noted in Highway Department plans.

Former monument apparently removed.

Corner lies in ditch on North side of Highway M-28.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64
REGISTERED LAND SURVEYOR
Billy D. Buckler