

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford Located In \_\_\_\_\_ Corner Code # \_\_\_\_\_  
(County)

1. Public Land Survey T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling in Section S 36 T 24N R 11W 13  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous Property in Section S 36 T 24N R 11W X  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Craig W. McVean, in a field survey on Oct. 23, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

13 - None

X - SW Corner of North 18 Acres (Prorated) of NE 1/4 of SE 1/4 Sec. 36 - None

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

13 - SE 1/16 Corner Sec. 36 - Set 2" Alum. Cap on 5/8" x 34" iron rebar per Standard BLM procedure. A found 1 3/16" x 3/16" strap iron at old fence corner to the south is N88°22'W 57.07' from 2" Alum. Cap.

X - SW Corner of North 18 Acres (Prorated) of NE 1/4 of SE 1/4 Sec. 36 - Set 2" Alum. Cap on 5/8" x 34" rebar by proportioning the acreage in the NE 1/4 of the SE 1/4 being 17.762 acres (N. 18 Acres - State deed) in the North and 21.709 Acres (22 Ac - private deed) in the south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

13 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar S72°W 5.65' to set N & T in S. side Tri. 9" R. Maple N65°W 25.46' to set N & T in SW side 16" R. Maple N43°E 15.60' to set N & T in NW side 8" Spruce S55°E 23.42' to set N & T in SW side 14" S. Maple NW 1' to set Blue Carsonite Post with loc. tag

X - SW Corner of North 18 Acres (Prorated) of NE 1/4 of SE 1/4 Sec. 36 Stamped 2" Alum. Cap on 5/8" x 34" iron rebar S27°E 20.72' to set N & T in W. side 22" Hemlock N4°W 55.25' to set N & T in E. side 12" W. Pine N45°E 11.34' to set N & T in SE side 11" Ash S50°W 5.83' to set N & T in SE side 4" S. Maple NW 1' to set Blue Carsonite Post with loc. tag

Signed by: Craig W. McVean  
Surveyor's Michigan License No.: 39088

Date: 11/14/2012

