

SURVEY & REMONUMENTATION

MAR 04 1998

LAND CORNER RECORDATION CERTIFICATE SECTION

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

1997 Alcona County Remonumentation

| FOR CORNERS OF--: | LOCATED IN--: | CORNER CODE NUMBER |
|--|---|----------------------|
| 1. PUBLIC LAND SURVEY_____ | T. <u>25N</u> N. S., R. <u>5E</u> E. W. | NE cor. S. 17 E-5 |
| 2. PROPERTY CONTROLL- ING IN SECTION_____ | , T. _____ N. S., R. _____ E. W. | |
| 3. MISCELLANEOUS PROPERTY IN SECTION_____ | , T. _____ N. S., R. _____ E. W. | |
| 4. LOT NO. _____, RECORDED PLAT _____ | | |
| 5. PRIVATE CLAIMS _____ | | |

APPROVED LAND CORNER
P A 345 of 1990
ALCONA COUNTY

Date 8/13/97
County Rep. D. B. Lee

RECORDED

Date September 8, 1997

REMON LIBER 1 PAGE 263

2:20 Time P M

Doris A. Gauthier
REGISTER OF DEEDS

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, John F. Oliver do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Aug. 20 1997, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

1845: G.L.O. - set post and referenced
1909: E. Chapelle - no description of corner
1914: A. Freer - gray boulder 18" long 7" wide 3" thick
1929: Dependent resurvey - fd. 4 x 4 wd. post - placed 6"x 24" conc. mon. with brass cap.
1978: N. Caldwell - fd. PK - replaced with 1/2" bar & cap
1990: Rowe Eng. - fd. 1/2" rod & cap - replaced w. 5/8" bar & cap in mon. box

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

fd. PK nail in old pavement with five accessories listed by Rowe Eng (1990) as shown in Liber 237, p. 527-8 (Deeds).

S 42°E / 69.58' / power pole
East / 41.61' / conc. pillar (top center)
S 38°W / 62.60' / power pole
S 52°W / 78.20' / NE corner of block house
East / 33.0' / 5/8" bar with #12018 cap

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

peer group discussion decides to set pavement box at PK nail location
field crew excavates for box finding original 1929 Dependent Resurvey conc. mon. the top 6" of which is broken off leaving the bar protruding

Placed pavement box with brass cap stamped to identify the corner on the bar in the conc. mon.

ABOVE WITNESSES FROM L. 237, p. 527-8 REMAIN

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 19840

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____