

FEB 07 2001

SECTION LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.19702000 Alcona County Remonumentation
FOR CORNERS OF— LOCATED IN—

1. PUBLIC LAND SURVEY— T. 27N N. S., R. 8E E. W.

2. PROPERTY CONTROLL- N. E.
ING IN SECTION— , T. S., R. W.3. MISCELLANEOUS N. E.
PROPERTY IN SECTION— , T. S., R. W.

4. LOT NO. —, RECORDED PLAT—

5. PRIVATE CLAIMS—

CORNER CODE NUMBER

D-11 ✓

Alcona County
Remonumentation
Liber 2 Page 63Filed for Record in
ALCONA COUNTY MICHIGAN
DORIS A GAUTHIER
On 09-20-2000 At 09:36 am.
LAND CORNER 9.00REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, John F. Oliver do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Aug. 10, 2000, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

D-11: 1838: GLO sur. by L. Clason - set post and referenced
1906: sur. by E. Chapelle - corner is called a post
1913: sur. by A. Freer - cor. is jagged stone 38 by 7 by 5 + on top
1995: sur. by J. Oliver - fd. 1/2" rod and cap
1996: sur. by J. Oliver - fd. 1/2" rod and cap

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-11: found 1/2" rod and cap - first three numbers 258

no evidence recovered from GLO survey of 1838

corner falls midway and on line between C-11 and E-11
Distances are compatable with previous surveys

corner location accepted as correct location for the corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11: placed pavement box with 1/2" rod and brass cap
referenced:

11" r. oak - S 35°E - 64.48 ft
7" ash - S35°W - 51.67 ft
15" r. oak - N 58°E - 81.01 ft
power pole - N 58°E - 81.01 ft

APPROVED LAND CORNER
P A 345 of 1990
ALCONA COUNTY
Date 7-6-2000
County Rep JD B. K

SIGNED BY _____ DATE Aug. 10, 2000

John F. Oliver
SURVEYOR'S MICHIGAN REGISTRATION NO. 19840

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM735
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

