

001 PAGE 40

APR 21 1994

1993 ALCONA COUNTY REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Al cona

(County)

Located In:

Corner Code ~~##~~

1. Public Land Survey

T 27/28N R 9E K 13 - 0.8 - L 13

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling in Section

S T R

S _____ T _____ R _____

3. Miscellaneous Property in Se

S _ _ _ T _ _ _ R

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat

5. Private Claims

Duane R. MacNeill in a field survey on **August 16,** 19**93**

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1838 - Set by U.S. Deputy Surveyor - 31.18 chains due East of K -13.

Witnesses:

Tam 12 N12W .05
Cedar 8 S31W -- (not recorded)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or accessories found after a thorough search.

Found concrete monument along line approx. 70' West of position called for by G.L.O. notes. This corner has been used in many previous surveys by local surveyors.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Alcona County Remonumentation Aluminum Cap, appropriately stamped, secured to 1/2" re-rod extending from concrete monument.

Witnesses:

Due West	6.12	10"	Ash
S 40° W	3.07	6"	Maple
N 45° E	17.42	4"	Balsam
N 55° W	6.05	4"	Maple

Witnesses were duplex nails bearing
brass washer stamped license #1923

Signed by

Date December 16, 1993

Surveyor's Michigan License No. 19237

FORM APPROVED BY MICHIGAN STATE

