

1993 ALCONA COUNTY REMONUMENTATION CORNER

APR 21 1994

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **COMMISSION**

Al cona

(County)

Located In:

Corner Code ~~77~~

1. Public Land Survey

T _____ R _____

T_____ R_____

T _____ R _____

T _____ R _____

2. Property Controlling in Section

S25/36T 28N R 9E

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Sec.

S _____ T _____ R _____

K 11 -0.6-L 11

4. Lot No. _____, Recorded Plat

5. Private Claims

I, Duane R. MacNeill, in a field survey on August 17,, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1838 - Set post by U.S. Deputy
Surveyor (meander corner)

Witnesses:

Cedar	6	S26W	18
Tam	6	N34W	26

Set 33.50 chains East of NW corner of Section 36.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or accessories found after a thorough search.

1993 - Remonumentation field crew found a concrete monument 2122.23' East of NW corner of Section 36.

No other monumentation found, due to the discrepancy in distance, the concrete monument is being accepted and recorded as a property controlling corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Alcona County Remonumentation Aluminum Cap, appropriately stamped, secured to the 1/2" re-rod extending from concrete monument.

Witnesses:

Due North	3.11	4"	Spruce
Due West	20.18	6"	Oak
Due East	18.31	7"	Cedar
S 40° E	34.12	4"	Pine

Witnesses were duplex nails bearing a brass washer stamped license #19237.

Signed by

Date **December 16, 1993**

Surveyor's Michigan License No. 19237

