

Approved by Alger County
Land Survey Re-monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 4-8-1995

Donald W. Kinnunen
Chairman

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alger

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 44N R 21W

C2

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

**SURVEY &
REMONUMENTATION**

MAY 10 1995

FILED

9:00 a.m.

APR 20 1995

DONALD W. KINNUNEN

REG. NO. 10000

Register of Deeds Stamp & File Number

COMMISSION

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert L. Jamros, in a field survey on December 07, 1994, 19 ,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

C2: PLS-Zelote B. Searls, DS, 1850, Set Qr. Section Post- Sugar 8", S.20 W., 15 links, Sugar 14", N.15 E., 17 links. Minneapolis, St.
Paul and Sault Ste. Marie Railroad right of way map, October 27, 1901, indicates corner as being 53.6 feet east of the centerline of
the railroad right of way., M.D.S.H., F.A.S. Project, 1971., Corner position shown, no measurements or monument, no references given.,
Alger County Road Commission Alignment Notes for the Eben-Trenary Road, Swan 1948. No corner indicated on the alignment notes.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C2: Found 1 3/4" GIP with 3 1/4" Brass cap marked to identify corner position, dated Nov. 2, 1917. Measured Alger County Road
Commission station distances along the Eben-Trenary Road to locate corner. Corner position checks well with record distances. Found
corner position 25.8 ft. west of the centerline of the Eben-Trenary Road and 52.3 ft. east of the centerline of an old railroad grade.
Corner position is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C2: Stamped P.A. 345 in existing brass capped galvanized iron pipe monument. Established reference trees w/ BT signs, blazed, scribed
and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Basswood 7', S.60 W., 84.27 feet, '1/4s
BT', Maple 8', N.47 W., 109.16 feet, '1/4s BT', P.Pole, S.87 E., 59.61 feet, 'BT', Steel witness post with Survey marker sign, N.83 W.,
2.0 feet. All bearings are magnetic.

| | A | B | C | D | E | F | G | H | I | J | K | L |
|----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 2 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 |
| 3 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 |
| 4 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 |
| 5 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 |
| 6 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 |
| 7 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 |
| 8 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 |
| 9 | 90 | 91 | 92 | 93 | 94 | 95 | 96 | 97 | 98 | 99 | 100 | 101 |
| 10 | 102 | 103 | 104 | 105 | 106 | 107 | 108 | 109 | 110 | 111 | 112 | 113 |
| 11 | 114 | 115 | 116 | 117 | 118 | 119 | 120 | 121 | 122 | 123 | 124 | 125 |
| 12 | 126 | 127 | 128 | 129 | 130 | 131 | 132 | 133 | 134 | 135 | 136 | 137 |
| 13 | 138 | 139 | 140 | 141 | 142 | 143 | 144 | 145 | 146 | 147 | 148 | 149 |

Signed by

Robert L. Jamros
25049

Date

12 April, 1995

Surveyor's Michigan License No.