

Herald W Carlson
Chairman

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

4-249

For corners in

Alger
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 45N R 21W

C4

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

Recorded July 15, 1994
at 8:00 o'clock A. M., and
Recorded in Liber 4 of Cor. Rec.
on Page 249

Paul W. Kimmman
Alger County Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert L. Jamros, in a field survey on September 28, 1993, 19 ,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C4: P.L.S., Z.B. Searls, DS, 1850. Set qr. sec. post. Hemlock 18, S.71 W., 11 links. Sugar 20, N.65 E., 47 links. Minneapolis, St.
Paul and Sault Ste. Marie Railroad Right of Way Map, January 19, 1901 and October 27, 1902. Corner noted 47.7 feet East of centerline
of railroad right of way. Edwin Swan, R.L.S., 1948 and 1949, Alignment notes for Eben-Trenary road, Alger County Road Commission.
Corner is approx. 38 feet West of Road centerline and 47 feet East of centerline of railroad tracks, no references given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C4: At the intersection of Maapala and Eben-Trenary roads found 2" G.I.P. w/3 1/4" brass cap, an Alger County Standard monument used
at the beginning of this century. Monument is dated Sept. 4, 1918, no record of setting this iron monument. Corner lies on westerly
side of road ditch, 37.5 feet west of the centerline of Eben-Trenary road and 47 feet east of abandoned Railroad grade, as shown on
A.C. Road Commission alignment plans. Established new references and is accepted as the best available evidence of the position of the
original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C4: Stamped P.A.345 in existing Brass
Cap G.I.P. Monument. Est. reference
trees w/BT signs, blazed, scribed and
painted. Set PK nails for measuring
w/brass I.D. washers in the following
reference trees. Maple 6", N.75 W.,
72.43 feet, '1/4S-BT'. Balsam 6", S.29
W., 25.82 feet, '1/4S-BT'. P.Pole, S.29
E., 33.49 feet, 'BT'. Twin Maple 5'-4",
N.57 E., 104.81 feet, '1/4S-BT'. Survey
Marker Sign S.69 W., 0.80 feet.

Signed by

Date

Surveyor's Michigan License No.