Approved by Aiger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 6-21 19 94

DAINCH.O. u

LAND CORNER RECORDATION CERTIFICATE

Justille Courson			7.4.4070	U - 75()	
Chairman	Filing Require	ement of Act 74, Mich.	P.A. 1970	1 200	
For corners in	•	•	1	·	
Alger	Located In:	Corner Code ##			
(County)				July 15, 1994	
			at 8:00	o'clock A. M., ar	nd
Public Land Survey	T <u>45N</u> R <u>21N</u> T R	-65		in Liber 4 of Cor.	<u>. Rec.</u>
,			on Page _		
	T R			De Die Minnene	-
	T R		Alger Co	unty Register of Deeds	s
2. Property Controlling S	_ T R				
in Section S	_ T R				
3. Miscellaneous S	_ T R		Register of I	Deeds Stamp & File N	lumber
Property in Sec. S	_ T R				
4. Lot No, Recorded I	Plat		A R	CDEFGHI	JKL
5. Private Claims					
			2 - 6-	╌┼╌┊╌┼╌╡╌┼╾┇╼┼	
			3	- - - - - - -	
			4 _ 7_		_1112
t in a finis	d outsian on	19	5		
f. Robert L. Janros in a field do hereby certify that under requirements	of P.A. 74 Michigan P.A.	of 1970, the corner points me	intioned 6 18		
in lines 1 and 2 above were in conforma	ince with regulations ar	nd rules therefore as require	d in the	17-16-115-1	1413·
current manual of survey instructions of t	he United States Depar	rtment of the Interior, Bureau	of Land	 	
Management or by a decree of a Court of L	aw and/or that the corne	er points mentioned in lines 3,	4 and 5 8 19.	22	2324
above were in conformance with the rules	of the Michigan Board	of Land Surveyors or by a Dec	cree of a	╶ ┧╼╁╼╂╾╂╾╂╾╂	
Court of Law; established, re-establish expressed below:	iea, monumentea, re-	monomented, recovered, ro	10	28 27	2625
•			11		
NOTE: Not more than 4 corners, al	I in the same town a	na range, may be recorde	-		
on this certificate.			12 -3'1-	32 33 34	35 - 36
			13		
A. Description of original monuments: P.L.S., Z.B. Searls, DS, 1850.					
B. Description of corner evidence for	ound and/or method	applied in restoring or ree	stablishing comer.		
C5: At intersection of West Louds S Monument is dated, Sept. 4, 1918 by Eben-Trenary road on the centerline rails of railroad have been removed Established new references and is ac	G.L.D. and E.A.H., no of West Louds Spur ro and the monument is a	record of setting iron co ad extended west, as shown pproximately 28 feet East	orner. Corner lies 5 n on A.C. Road Commis of the centerline of	4 feet west of centerl sion alignment plans. the dirt grade of the	line Iron
* .		,			
		,			
C. Description of monument for cor C5: Stamped P.A.345 in existing Bra Cap G.I.P. Mon. Est. reference poin and reference trees w/BT signs, blaz scribed and painted. Set PK nails f measuring w/brass I.D. washers. Powe Pole w/Anchors, N.35 E., 44.28 feet, "BT". Cedar Cluster, 3-7", 1-6", S. E., 1.18 feet, "S17-BT". Elm 6", S. W., 46.58 feet, "S18-BT". 6 foot st fence post w/2' Bury & Marker Sign,	ts ed, or r 73 6 eel	established to perpetuate	locating the position	n of the corner:	
W., 7.48 feet from face. Sur. Marker					
Sign, West, 0.60 ft	// /				
La l.	+ 1		1 dans	1994	
Signed by ##	ww. fern	Date _	- Lune	- 3141	
Surveyor's Michigan License No	/ Z5	841	FORM APPROVED BY MICH	GAN STATE BOARD OF LAND SURVEY	YORS, JAN. 26, 19 WISED MAY 14, 19

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 . REVISED MAY 14, 1975 REVISED JAN., 1983