MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_46_ NR_17_B.

			AlgerCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 16 & 17
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Briss sop
WIT TNESSES	то	CORNER	
			_ 8" Cecer - 1 74 H - 24 Links
			9#_0edar = # 62_E = 30 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously been lecated by unknown. One probable original D.T. still in place, down, in poor condition.

Corner was placed and witnessed May 7, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/21/54