

SURVEY & REMONUMENTATION

FEB 19 1998

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-10-1997

SECTION

05-68

Donald W. Carlson
Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

46
(County)

Located In:

Corner Code #

FILED
TIME 8:30 A.M.

DEC 17 1997

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

1. Public Land Survey	T	<u>46</u>	R	<u>17</u>	B3
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T		
	S		T		
3. Miscellaneous	S		T		
Property in Section	S		T		

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert L. Jamros, in a field survey on November 16, 1997, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B3: PLS - William Ives, OS, 1850 * Set quarter section post * Yellow Birch 16, S.20 E., 2 links * Sugar 22, N.17 E., 21 links **** George L. Depew, County Surveyor, 1915 * Set standard iron corner from original field notes **** Robert L. Jamros, RLS, 1986 * Found galv. iron pipe w/3 inch brass cap * Corner monument in good condition. Established new corner witness trees as follows - Maple 18, N.83 W., 36.27 feet * Maple 14, S.11 E., 25.55 feet * Maple 16, N.50 E., 77.90 feet * Maple 9, N.40 W., 53.83 feet * Recorded in Liber 3, Page 347, Alger County Corner records * No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B3: Found Alger County standard monument w/3 inch brass cap, dated 1915, and 3 BT's of the 1986 report * Renewed exist. BT's and established 1 additional reference tree. * Monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B3: Exist. Alger County standard monument as stamped to identify corner position * Set PK nails w.Alum. I.D. washers for measure in the following - Maple 24, S.56 E., 65.9 feet * Exist. BT, Maple 24, N.53 E., 77.90 feet * Exist. BT, Maple 20, N.77 W., 36.27 feet * Exist. BT, Maple 9, N.35 W., 53.83 feet * All bearings are magnetic.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

Robert L. Jamros
Surveyor's Michigan License No. 25849

Date

12/10/1997

