

SURVEY &  
REMONUMENTATION

FEB 19 1998

Approved by Alger County  
Land Survey Remonumentation  
Peer Group Under Act 343 of  
P.A. of 1990 On 12-10-1997

SECTION

05-65

Gerald W. Carlson  
Chairman

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

\_\_\_\_\_ (County)

Located in:

Corner Code #

- |                                      |   |           |   |           |           |
|--------------------------------------|---|-----------|---|-----------|-----------|
| 1. Public Land Survey                | T | <u>46</u> | R | <u>17</u> | <u>C3</u> |
|                                      | T | _____     | R | _____     | _____     |
|                                      | T | _____     | R | _____     | _____     |
|                                      | T | _____     | R | _____     | _____     |
| 2. Property Controlling in Section   | S | _____     | T | _____     | _____     |
|                                      | S | _____     | T | _____     | _____     |
| 3. Miscellaneous Property in Section | S | _____     | T | _____     | _____     |
|                                      | S | _____     | T | _____     | _____     |

FILED  
TIME 8:30 Am

DEC 17 1997

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert L. Jamros, in a field survey on October 02, 1997, 19 \_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C3: PLS - William Lee, OS, 1950 \* Set post corner of Sections 5, 6, 7 & 8 \* Sugar 18, N.19 W., 29 links \* Sugar 22, S.74 E., 30 links \*\*\*\*\* Munising Railway Company, East Branch Extension \* R.C. Young, Chief Engineer, 1904 \* Section corner is shown 529 feet West of centerline of railroad at Station 101+05 \*\*\*\*\* Set standard iron corner from original field notes \* Walter W. Gleason, County Surveyor, 1913 \*\*\*\*\* Alger County Road Commission \* Van Meer-Shingleton Road \* Corner shown at Station 106+12.4 \* George L. Depew, Engineer, 1923 \*\*\*\*\* Munising-Shingleton Road \* Corner is shown (no detail) on construction plans, M.S.H.D., 1958 \*\*\*\*\* Land Corner Record, M.D. of C. \* Monument box, 2 links West of centerline of M-94 at East-West road junction \* Billy D. Buckler, 1960 \* No references given \* Recorded in Liber 2, Page 190, Alger County Corner Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C3: Found 1 inch iron bar in monument box \* Identified by description on recorded 1960 report, 2 links West of centerline of County Road H-15 (old M-94) at East-West road junction \* Corner position sets well with record information and distances North and South \* Distance from corner position to old railroad grade was measured at 527 feet \* Replaced exist. monument and established reference objects \* Corner position has been accepted and used in area surveys. \* Monument position as found is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C3: Replaced 1 inch iron bar with 5/8 inch by 18 inch Rebar w/Berntsen Alum. cap no. RBD 5325, stamped to identify corner position in monument box, 1.3 feet West of centerline of pavement at East-West road junction \* Established reference objects w/RT signs, blazed, scribed and painted \* Set PK nails for measuring w/brass I.D. washers in the following - Power Pole w/guy, S.17 W., 57.29 feet, "BT" \* Telephone Pedestal Post, S.17 E., 51.56 feet, "BT" \* Elm 6, N.20 E., 113.7 feet, "BT" \* 2 1/4 inch galv. Sign Post, N.41 W., 39.55 feet \* All bearings are magnetic.

Signed by Robert L. Jamros

Surveyor's Michigan License No. 25049

Date 12/10/1997

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

