

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Alger Co.

2 Corners.

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>46</u> N. <u>17</u> E. <u>W.</u>	<u>C-7</u>
2. PROPERTY CONTROLL-18 ING IN SECTION_____	T. <u>46</u> N. <u>17</u> E. <u>W.</u>	<u>14-Sec.18</u>
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ E. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-13- 19 81, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

C-7 Sec. Cor. 17-18-19-20  
14-Sec.18 South 1/16 Corner, on East side of Section 18.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-7 Re-established corner on center line of N-S road and by single proportionate measure bet. Sec. Cor.; one mile North and quarter corner; one half mile South.  
14-Sec.18 Placed corner midway between Sec. Cor. to South and computed 1/4 cor. to North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Buried a 36" T-Iron in Center of Blacktop Road at both corners. Bearings are:

C-7 16" W. Spruce, N49°E, 50.7' & 7" W. Birch, N68°W, 41.5'.  
14-Sec.18 Geological Survey Monument, with Brass Cap ( 3 TA 1980), S21°E, 57.0' & Power Pole, S23°E, 55.5' & Power Pole, S69°W, 24.9'.  
Corner is 21.0' North of road to East and 37.0' South of old grade, NW-SE.

SIGNED BY Billy D. Buckler

DATE 7-13-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

