

SURVEY & MONUMENTATION

JAN 18 2001

For corners in **SECTION**

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Alger County
Land Survey Monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Donald W. Kinnunen
Chairman

05-223

Alger
(County)

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 46N | R | 17W | E05 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | | R |
| | S | | T | | R |
| 3. Miscellaneous | S | | T | | R |
| Property in Section | S | | T | | R |
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on November 01, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E05: PLS William Ives, DS, 1850. Post set corner of Sections 8, 9, 16 and 17. Cedar 16", N.60°W., 25 links. Cedar 10", S.14°E., 13 links. ***** Alger County. Geo. L. DePew, CS, 1917. Set iron corner from Government field notes. No references given. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Found 2" iron pipe with 3" brass cap, dated 1917 by G.L.O. and H.J.H. Set witnesses: Cedar 12" (S9 NBT) N.58°E., 37 links. Cedar 10" (S17 NBT) S.26°W., 22.5 links. Liber 2, Page 196, Alger County records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E05: Found 2" iron pipe with 3" brass cap and 1 NBT of the 1960 report, in good condition. NBT bearing Northeast from corner position is dead and down. No G.L.O. evidence was found at corner position. Existing monument position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E05: Existing 2" iron pipe with 3" brass cap as found. Renewed existing NBT with BT signs and paint. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following. Ex. NBT, Cedar 14", S.36°W., 14.94 feet (S17 NBT). Maple 12", N.49°W., 31.65 feet (S8 BT). Cedar 16", N.26°E., 33.70 feet (S9 BT). Spruce 8", S.81°E., 16.55 feet (S16 BT). Survey marker sign on 6 foot steel post, N.80°W., 0.70 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date

Dec. 17, 2000

Surveyor's Michigan License No.

25849

