

JAN 18 2001

Approved by Alger County
Land Survey Monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Donald W. Kinnunen
Chairman

05-225

For corners in **SECTION**

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located In:

Corner Code #

1. Public Land Survey

T 46N R 17W G01 ✓

T 47N R 17W G13

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

FILED
TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	6	5	4	3	2	1						
5													
6	18	17	16	15	14	13							
7													
8	19	18	17	16	15	14	13	12	11	10	9	8	7
9													
10	30	29	28	27	26	25							
11													
12	31	30	29	28	27	26	25	24	23	22	21	20	19
13													

I, Robert L. Jamros, in a field survey on July 19, 2000

do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G01: PLS William A. Burt, DS, 1841. Set corner of Sections 33 and 34. (Blank) 12", N.81°E., 35 links. (Blank) 14", N.28°W., 28 links. ***** PLS William Ives, DS, 1850. Section corner on North boundary. Beech 14", S.36°E., 44 links. Beech 8", S.72°W., 29 links. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap by double proportionate measurement using section corners to East, West, South and 1/4 corner North. Hemlock 10", (S34 NBT) N.65°E., 44 links. Maple 10", (S3 NBT) S.22°E., 28 links. Maple 12", (S33 NBT) N.30°W., 54 links. Liber 2, Page 209, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G01: Found 1" iron pipe with 4" brass cap and 2 NBT's of the 1960 report in good condition. NBT bearing Northeast from corner gone. Measurements between corners in this area agree well with measurements from this corner West and South. Existing monument position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G01: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT's with BT signs and paint. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, Maple 30", N.29°W., 35.37 feet (blaze scars); Ex. NBT, Maple 16", S.19°E., 18.96 feet (blaze scars); Maple 14", S.72°W., 10.51 feet (S4 BT); Maple 14", N.62°E., 35.47 feet (S34 BT). Survey marker sign on 6 foot steel post, S.45°E., 1.0 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date Dec. 17, 2000

Surveyor's Michigan License No. 25849

