

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alger

(County)

Located In:

Corner Code #

1. Public Land Survey

T___ R___
T___ R___
T___ R___
T___ R___
S 26 T 46N R 17W 16
S 26 T 46N R 17W 13
S___ T___ R___
S___ T___ R___

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

13 Oct 03 2002
16 Oct 30 2002

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
(16-Sec. 26) East 1/16 corner between Sections 26 and 35. Not established in the original survey. Found no subsequent record.
(13-Sec. 26) Southeast 1/16 corner. Not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 26) Established the corner midway and on a line of mean true bearing between Quarter corner 1326.90' West and Section corner 1326.90' East. The position is approx. 82' south of the centerline stripe of Highway M-28.
(13-Sec. 26) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. 1/16 corners #9 and #14 were left unmonumented by this survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx36" I.pipe with 4" alum.
MDNR cap. Blazed, scribed, and set
measuring nails in:
5" Cedar S52E 8.65' "E1/16 BT"
12" Spruce S69E 19.05' do
10" Spruce S08E 21.15' do
4" Cedar S30E 17.5' do
Cedar post adjacent. Bearings are
magnetic. Distances are to nail with
tag.

(13) Set 1"IDx36" I.pipe with 4" alum.
MDNR cap. Blazed, scribed, and set
measuring nails in:
12" Balsam S16W 8.2' "SE1/16 BT"
3" Maple S54E 4.25' do
8" Spruce N30E 16.95' do
3" Balsam N16W 10.6' do
Made the monument firm in a mound of
rock. Bearings are magnetic. Distances
are to nail with tag.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/5/02