

SURVEY & MONUMENTATION

JAN 18 2001

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Guillelmo Carlson
Chairman

05-224

For corners in **SECTION**

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located In:

Corner Code #

- | | | | | | |
|---------------------------------------|---|-----|---|-----|-------|
| 1. Public Land Survey | T | 46N | R | 17W | F01 |
| | T | 47N | R | 17W | F13 ✓ |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling In Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Section | S | | T | R | |
| 4. Lot No. _____, Recorded Plat _____ | | | | | |
| 5. Private Claims _____ | | | | | |

FILED
TIME 8:50 Am.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, Robert L. Jamros, in a field survey on July 19, 2000
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F01: PLS William A. Burt, DS, 1841. Set quarter section post. Sugar 12", N.28°E., 57 links. Sugar 16", N.30°W., 45 links. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap midway and on line between section corners. No evidence of original corner. Soft Maple 7" (¼S NBT) N.65°W., 22 links. Soft Maple 10", (¼S NBT) S.04°E., 26 links. Liber 2, Page 210, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F01: Found 1" iron pipe with 4" brass cap and 2 NBT's of the 1960 report in good condition. Existing monument lies at midpoint and 1.6 feet South of line between section corners ¼ mile West and East. Existing monument is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F01: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT with BT signs and paint. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, Maple 10", N.63°W., 14.84 feet (blaze scars); Ex. NBT, Maple 16", S01°E., 17.34 feet (blaze scars); Maple 7", N.86°E., 10.28 feet (¼S BT); Maple 7", N.13°E., 8.55 feet (¼S BT). Survey marker set on 6 foot steel post, N.50°E., 1.0 feet. All bearings are magnetic.

Signed by Robert L. Jamros

Date Dec. 17, 2000

Surveyor's Michigan License No. 25849

