

SURVEY & MONUMENTATION

JAN 18 2001

For corners in

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located in:

Corner Code #

1. Public Land Survey T 47N R 22W I09
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R
4. Lot No. , Recorded Plat
5. Private Claims

Approved by Alger County
Land Survey Monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Handwritten Signature
Chairman

05-230

FILED

TIME 8:50 A.M.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Robert L. Jamros, in a field survey on June 3, 2000

do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I09: PLS Alfred Millard, DS, 1852. Corrected between Sections 26 and 27. Set post corner of Sections 22, 23, 26 and 27. Hemlock 12", N.72°E., 26 links. Maple 12", S.50°W., 40 links. ***** C.C.I. Co., Land and Timber reports. S. Lowney, Jr., cruiser, 1948. R.H. Ewalt, cruiser, 1948. David B. Whittier, cruiser, 1950. Lionel Spencer, cruiser, 1964. G.A. Moote, cruiser, 1965. All cruisers found an iron pipe with brass cap. Unrecorded reports. ***** C.C.I. Co., Land Corner Record. Robin D. Steinhoff, cruiser, 1967. Iron pipe with brass cap. Hemlock 5", N.50°W., 13 links. Hemlock 5", S.67°E., 10.5 links. Unrecorded report. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I09: Found 2" cast steel monument with 3/4" brass cap stamped to identify, dated November 18, 1910. Also found an existing BT bearing Northwest from monument position. Corner monument believed to be set by L.E. Adams, County Surveyor, 1909-1913. No record was found as part of the research for this corner. No original evidence was found. Corner monument as found is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I09: Existing 2" cast steel monument with 3/4" brass cap. Renewed existing BT with BT signs and paint. Established new reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. BT, Hemlock 9", N.43°W., 8.81 feet (blaze scars); Hemlock 7", N.52°E., 8.39 feet (S23 BT); Maple 7", S.34°E., 42.00 feet (S26 BT); Hemlock 20", S.60°W., 52.38 feet (S27 BT). Survey marker sign on 6 foot steel post, S.01°E., 2.6 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date Dec. 17, 2000

Surveyor's Michigan License No.

25849

