

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 6 T 48N R 15W	13
	S T R	(GCDB 160620)
	S 6 T 48N R 15W	7
	S T R	(GCDB 200660)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 13 06/26/14  
7 06/18/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 6) Southeast 1/16 corner, Section 6. Not previously monumented.

(7-Sec. 6) North 1/16 corner between Sections 5 and 6. Not previously monumented. The 1852 US GLO  
plat of this township shows this corner to be 20.00 chains north of the Quarter corner and 20.25  
chains south of the Section corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 6) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

(7-Sec. 6) Established the position for the corner on the Section line between Quarter corner  
1318.44' south and Section corner 1334.88' north, being proportionate to the dimensions shown on the  
US GLO plat.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
28" W.Pine S74°E 11.35' mrkd "SE1/16 BT"  
11" W.Pine S55°W 17.25' do  
9" W.Pine N60°W 16.5' do  
10" Hemlock N48°E 17.55' do  
E= 8059376.923 N= 200134.892

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
19" W.Pine N25°W 12.75' mrkd "N1/16 BT"  
20" Hemlock N30°E 18.25' do  
20" W.Pine West 53.55' do  
9" Maple S46°E 15.2' do  
E= 8059774.854 N= 200944.049

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID RK0012: N= 200478.710 m. E= 8059786.467 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/30/2014

For the Michigan Department of Natural Resources, Forest Resources Division

