

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger (County) Located In: Corner Code #
1. Public Land Survey T R
2. Property Controlling in Section S 5 T 48N R 15W 11 (GCDB 220620)
3. Miscellaneous Property in Sec. S 5 T 48N R 15W 13 (GCDB 260620)
4. Lot No. , Recorded Plat
5. Private Claims

I, Stephan J. Szyszkoski, in a field survey on 11 06/18/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- (11-Sec. 5) Southwest 1/16 corner, Section 5. Not previously monumented.
- (13-Sec. 5) Southeast 1/16 corner, Section 5. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (11-Sec. 5) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.
- (13-Sec. 5) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- (11) Set 5/8"x24" rebar with plastic MDNR cap flush with ground surface. The position falls 5.5' SW of the W'ly edge of pavement of the County Rd. H58. Set measuring nail with MDNR tag in the side of: 15" R.Pine N66°W 66.0' mrkd "SW1/16 BT" 6" Maple S61°W 35.15' do 5" Maple S03°E 54.7' do 8" R.Pine N12°E 61.6' do E= 8060186.700 N= 200146.462
- (13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Hemlock N88°E 5.55' mrkd "SE1/16 BT" 12" W.Pine S61°W 23.25' do 8" Hemlock N50°W 23.85' do 10" Maple N11°E 26.4' do E= 8060998.020 N= 200158.352

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum). Coord. Ref.=NGS PID RK0012: N= 200478.710 m. E= 8059786.467 m.

Signed by [Signature] Date 07/30/2014
Surveyor's Michigan License No. 33986
For the Michigan Department of Natural Resources, Forest Resources Division