

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger Located In: Corner Code #
1. Public Land Survey T 48N R 15W B3
2. Property Controlling in Section S 6 T 48N R 15W 12
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numerical data for the Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 12 06/26/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B3) Quarter corner common to Sections 6 and 7. 1851 - Established by Geo. Adair, Deputy Surveyor, on the Section line between Section corners 40.00 ch. East and 36.64 ch. West. Set post. Beech 12" N56°W 19 links, Spruce 13" S12°E 12 links. Found no subsequent record.

(12-Sec. 6) Center-South 1/16 corner, Section 6. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B3) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the Section line between Section corners 2649.83' east and 2427.25' west, being proportionate to the 1851 record.

(12-Sec. 6) Established the position for the corner midway and on a straight line between Quarter corner 1320.96' south and the intersection of 1/4 lines of Section 6 1320.96' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 19" R.Pine S36°W 10.2' mrkd "1/4S NBT" 6" R.Pine N66°E 9.2' do 6" R.Pine N56°W 19.25' do 6" W.Pine S81°W 17.9' do E= 8058976.672 N= 199726.722

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 9" Maple N27°W 47.9' mrkd "S1/16 BT" 7" Maple N23°E 13.65' do 5" Maple S17°E 2.95' do 4" Maple S36°W 10.15' do E= 8058972.794 N= 200129.280

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum) Coord. Ref.=NGS PID RK0012: N= 200478.710 m. E= 8059786.467 m.

Signed by [Signature] Date 07/30/2014
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

