

**JAN 18 2001**

Approved by Alger County  
Land Survey Monumentation  
Peer Group Under Act 345 of  
P.A. of 1990 On 12-13-2000  
*Donald W. Kinnunen*  
Chairman

05-209

For corners in **SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

Alger  
(County)

Located In:

Corner Code #

- |   |   |     |   |     |     |
|---|---|-----|---|-----|-----|
| 1. Public Land Survey                   | T | 48N | R | 15W | D09 |
|   | T |     | R |     |     |
|   | T |     | R |     |     |
|   | T |     | R |     |     |
| 2. Property Controlling<br>in Section   | S |     | T | R   |     |
|   | S |     | T | R   |     |
| 3. Miscellaneous<br>Property in Section | S |     | T | R   |     |
|   | S |     | T | R   |     |

**FILED**  
**TIME 8:50 AM**

**DEC 20 2000**

**DONALD W. KINNUNEN**  
**REGISTER OF DEEDS**  
**ALGER COUNTY, MI**

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, Robert L. Jamros, in a field survey on April 18, 2000,  
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, recovered, found  
as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

**D09:** PLS Geo. E. Adair, DS, 1851. Set quarter section post. Maple 11", N.42°E., 22 links.  
W. Pine 16", S.36°W., 37 links. \*\*\*\*\* Michigan Department of Conservation, Forestry Division.  
Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap from original W. Pine BT  
bearing S.36°W., 37 links. W. Pine stub 16", 6 feet high (1/4S NBT) N.01°E., 90 links. W.  
Pine stub 24", 6 feet high (1/4S NBT) N.48°E., 60 links. W. Pine stump 24" (NBT) West, 54  
links. Liber 2, Page 149, Alger County corner records. \*\*\*\*\* No other subsequent restoration  
of record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

**D09:** Found 1" iron pipe with 4" brass cap of the 1960 report, with all accessories lost.  
Existing corner monument as found lies 13.4 feet North and 7.3 feet West of the midpoint  
position between section corners. Existing corner monument as found is accepted as a careful  
and faithful reestablishment of the position of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

**D09:** Existing 1" iron pipe with 4" brass cap as found. Established reference trees with BT  
signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in  
the following: R. Pine 20", S.32°E., 15.87 feet (1/4S BT); R. Pine 18", S.52°W., 111.08 feet  
(1/4S BT); R. Pine 14", N.07°W., 63.00 feet (1/4S BT); R. Pine 16", N.63°E., 85.78 feet (1/4S  
BT). Survey marker sign on 6 foot steel post, S.19°W., 1.0 feet. All bearings are magnetic.

Signed by *Robert L. Jamros* Date DEC 17, 2000

Surveyor's Michigan License No. 25849

