

JAN 18 2001

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 845 of
P.A. of 1990 On 12-13-2000

Harold Carlson
Chairman

05-211

For corners in SECTION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alger (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>48N</u> R <u>15W</u>	<u>G08</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
4. Lot No. <u> </u> , Recorded Plat <u> </u>		
5. Private Claims <u> </u>		

FILED
TIME 8:50 Am.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on September 26, 2000
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

G08: PLS Geo. E. Adair, DS, 1851. Set quarter section post. Y. Birch 11", N.32°W., 30 links. Spruce 13", S.65° 30'E., 22 links. *****Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap at single proportionate measurement between section corner to North and line tree 8.76 chains South. This line tree is still standing though badly burned. Notches are very plain. W. Pine stump 28" (4S NBT) S.25°W., 45 links. W. Pine stump 30" (4S NBT) S.74°E., 99 links. W. Pine stub 14" (4S NBT) N.06°E., 160 links. Liber 2, Page 157, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G08: Found 1" iron pipe with 4" brass cap and 2 of the NBT's of the 1960 report in good condition. NBT bearing Northeast from corner has been destroyed and lost. Existing monument as found lies at proportionate location and 1.4 feet West of a straight line between corners 1/2 mile South and North. Existing monument as found is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G08: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT's with BT signs and paint. Established new references with BT signs, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W. Pine stump 28", S.29°W., 30.35 feet (NBT); Ex. NBT, W. Pine stump 30", S.74°E., 65.66 feet (NBT); W. Pine stump 40", N.34°E., 81.62 feet (BT); W. Pine stump 30", N.51°W., 48.17 feet (BT). Survey marker sign on 6 foot steel post, S.06°E., 1.2 feet. All bearings are magnetic.

Signed by Robert L. Jamros Date Dec 17, 2000
Surveyor's Michigan License No. 25849

