

JUL 30 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alger _____ (County)

Located In:

Corner Code #

1. Public Land Survey

T 50N R 3W

M12_

T _____ R _____

T _____ R _____

T _____ R _____

T R

2. Property Controlling in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Section

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat

5. Private Claims

I, Robert L. Jamros, in a field survey on March 06, 1996, 19 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M12: PLS-John Hurt, DS, 1841, Set qr. section post - N.Pine 6", S.21 W., 22 links, N.Pine 6", N.12 W., 25 links.***** Michigan Department of Natural Resources, Billy D. Buckler, RLS, 1975, Corner re-established at record distance North of township corner and on same bearing as the mile south. Found a wood post 11.3 feet West and 2.0 feet North. No evidence of original corner. Set 1" pipe with 4" Aluminum cap and established the following references - J.Pine 6", N.75 E., 11.4 feet, J.Pine 6", S.78 W., 15.3 feet. Recorded in Liber one on page 214, Luce County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M12: Found 1' G.I.P. with 4" Aluminum Cap and a 4" flat faced wood post, scribed. Also found two existing bearing trees as described in the report of 1975 in good condition. Both existing bearing trees renewed to current Alger County standards. Information acquired from the Michigan Department of Natural Resources documenting the method at which corner position was reestablished follows accepted methods. Established two additional witness trees. Monument position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M12: Stamped P.A. 345 in existing four inch Aluminum capped Department of Conservation Monument. Renewed existing reference trees w/ BT signs and paint. Established additional reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Ex. Jack Pine 10", N.78 E., 11.63 feet, ' 1/4s NBT ', Ex. Jack Pine 7", N.76 W., 15.57 feet, ' 1/4s NBT ', Jack Pine 6", S.32 1/2 E., 24.54 feet, ' 1/4s BT ', Jack Pine 7", S.58 W., 29.88 feet, ' 1/4s BT '. Survey marker sign on six foot steel post, N.12 W., 0.80 feet. All bearings are magnetic.

Signed by

Surveyor's Michigan License No.

Date _____

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

FILED
TIME 3:00 p.m.

JUN 27 1996

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number