

ALLEGAN COUNTY REMONUMENTATION
 LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

1995 DEC 14, PM 2:33
 REGISTER OF DEEDS
 ALLEGAN COUNTY, MICHIGAN
 FILED

SURVEY &
 REMONUMENTATION

APR 29 1996

COMMISSIONER

For corners in

ALLEGAN (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>1N</u> R <u>11W</u>	<u>M-4 (E1, 12)</u> <u>GUN PLAIN TWP</u>
	T ___ R ___	___
	T ___ R ___	___
	T ___ R ___	___
2. Property Controlling in Section	S ___ T ___ R ___	___
	S ___ T ___ R ___	___
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	___
	S ___ T ___ R ___	___
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, BASIL ANDRESS, in a field survey on 2 DEC, 19 95
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
 Court of Law, established, re-established, monumented, re-monumented, recovered, found as
 expressed below.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	19	20	21	22	23	24				
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 G.L.O.
 40.00 SET QR SEC POST J.W. HICKS, C.S.
 Y. OAK 10 S 31° W 19 CIRCA: 1880'S
 W. OAK 9 N 40½° W 31 STONE
 DIST W TO L-4 40.60
 DIST S TO M-5 40.23½

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 FD ½" IRON IN MON. BOX
 DIST SOUTH TO M-5 2662.88 (BUDZIK'S SURVEY DATA)
 A-4 (T-1N, R-10W) (½" IRON IN MON BOX) SOUTH 5.71'
 A-4 WAS RECORDED TWICE AS M-4
 - L.C.R.C. L-03, P-307 5-11-81
 - L.C.R.C. L-03, P-318 7-27-81
 REPLACED ½" IRON W/ STD ALLEGAN CO. MON. (¾" X 24" IRON W/ CAP) AND IS
 ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL
 CORNER.

APPROVED REMONUMENTATION CORNER
 P.A. 345 OP 1990
 ALLEGAN COUNTY
 DATE APPROVED 11-14-95
 COUNTY REP. Paul Wilson

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 STD. ALLEGAN CO. MON. (¾" X 24" IRON W/ CAP) IN MON. BOX
 16d REMON TAG NW SDE PP S 55° W 81.50'
 16d REMON TAG SE SDE 18" OAK S 30° W 76.08
 16d REMON TAG SW SDE T.P. S 30° E 54.42'
 S. EDGE STOP SIGN POST N 70° E 38.80'
 C/L DOSTER RD WEST 2.5'
 C/L 109TH AVE TO WEST IS SOUTH 7.5'±
 A-4 (T-1N, R-10W) (STD. BARRY CO. MON.) SOUTH 5.66'



Signed by Basil Andress Date 4 Dec 95
 Surveyor's Michigan License No. 30076